

Refere nci a	Ø	Pa CILso	d k	D3	s	s1	a1	W	L3	A	D	d1	C1	B	d4	D5	L5	L7	H1	L4	D2	
CD/ HR2 5-32	32	25-32	1,25	10,05	M10X1,25	17	14	13	17	20	13°	10	12.9	10.5	14	15	19	6.5	15	43	57	28
CD/ HR4 0	40	M12X1,25	19	22	13°	12	15.4	12	16	17.5	22	6.5	17	50	66	32						
CD/ HR5 0-63	50-63	M16X1,5	22	28	15°	16	19.3	15	21	22	27	8	23	64	85	42						
CD/ HR8 0-100	80-100	M20X1,5	30	33	14°	20	24.3	18	25	27.5	34	10	27	77	102	50						
CD/ HR1 25	125	M27X2	41	51	17°	30	34.8	25	37	40	50	15	36	110	145	70						
CD/ HR1 60	160-200	M36X2	50	56	19°	35	37.7	28	43	46	58	17	41	125	165	80						

