

# MANOMETROS

## SECOS

M.SECO Ø63 1/4 POS. 0-10 BAR/PSI



Referencia: **M6310**

### Descripción

Manómetro seco de salida roscada central posterior. La rosca es de tipo cónico ISO 7/l.

### Características

| Referencia | F   | Rango (bar) | A  | C  | P  |
|------------|-----|-------------|----|----|----|
| M4001,6    | 1/8 | 0-1,6       | 40 | 40 | 10 |
| M4002,5    | 1/8 | 0-2,5       | 40 | 40 | 10 |
| M4004      | 1/8 | 0-4         | 40 | 40 | 10 |
| M4006      | 1/8 | 0-6         | 40 | 40 | 10 |
| M4010      | 1/8 | 0-10        | 40 | 40 | 10 |
| M4012      | 1/8 | 0-12        | 40 | 40 | 10 |
| M4016      | 1/8 | 0-16        | 40 | 40 | 10 |
| M4025      | 1/8 | 0-25        | 40 | 40 | 10 |
| M5001,6    | 1/8 | 0-1,6       | 50 | 46 | 10 |
| M5002,5    | 1/8 | 1-2,5       | 50 | 46 | 10 |
| M5004      | 1/8 | 0-4         | 50 | 46 | 10 |
| M5006      | 1/8 | 0-6         | 50 | 46 | 10 |
| M5010      | 1/8 | 0-10        | 50 | 46 | 10 |
| M5012      | 1/8 | 0-12        | 50 | 46 | 10 |
| M5016      | 1/8 | 0-16        | 50 | 46 | 10 |
| M5025      | 1/8 | 0-25        | 50 | 46 | 10 |
| M6301,6    | 1/4 | 0-1,6       | 63 | 50 | 12 |
| M6302,5    | 1/4 | 0-2,5       | 63 | 50 | 12 |
| M6304      | 1/4 | 0-4         | 63 | 50 | 12 |
| M6306      | 1/4 | 0-6         | 63 | 50 | 12 |
| M6310      | 1/4 | 0-10        | 63 | 50 | 12 |
| M6312      | 1/4 | 0-12        | 63 | 50 | 12 |
| M6316      | 1/4 | 0-16        | 63 | 50 | 12 |
| M6325      | 1/4 | 0-25        | 63 | 50 | 12 |

